

**PIX DIGITAL TENSION METER**

**STANDARDS:** THE DIGITAL TENSION METER IS USED TO CHECK THE TENSION OF DRIVE BELTS BY MEANS OF FREQUENCY MEASUREMENT.



<b>Range of measurement:</b>	10-600Hz
<b>Measuring precision:</b>	10-400Hz +/- 1%
	400-600Hz +/- 2%
	+/- 1 digit
<b>Measuring method:</b>	non contact acoustic with background noise suppression

<b>Voltage supply:</b>	2*1,5V Mignon (LR06) AA
<b>Power consumption:</b>	< 25 mA
<b>Display:</b>	LCD 2 lines of 8 characters
<b>Working temperature:</b>	0 to +50° C
<b>Storage temperature:</b>	-20 to +60°C