

**PIX PULLEY GAUGE
STANDARDS:**



PIX Pulley Gauges

PIX Pulley Gauges are specially designed for checking the profiles of the grooves of various conventional and dual section pulleys.

Groove Checking Procedure

1. Identify the pulley gauge to be used according to section and its diameter.
2. Measure the groove by inserting the gauge. Identify if any clearance lies between the side wall of groove & the gauge.
3. Measure the present clearance using the Feeler Gauge.